

MARIENVILLE RANGER DISTRICT

OIL AND GAS INSPECTION REPORT

OGM Case Number: 243 Date of Inspection: 06-02-08
 Weather Conditions: sunny and warm, 60's Persons On-Site: 3
 Warrant/Lot Number: 2752, Lot 8 Mineral Owner/Leasee: Duhring Resource Co.
 Project: Cut, Skid and Deck Inspector: David Cotterman
 Discussed Operation With: Marty Grove, John Cochran
 Equipment On-Site: TJ skidder, Excavator, dozer
 Activity On-Site: yes

INSPECTION ITEMS and RESOURCE CONCERNS

Erosion		FS System Roads	
Minor oil, gas, brine leak		Non-FS System Roads	
Major oil, gas, brine spill		Drainage Structures	
Safety Hazards		Tank Concerns	
Unauthorized Development		Re-Vegetation	
Well Head Leaks		Slash Disposal	
Sump Ponds		Electric Lines	
Timber Removal		Pipe Lines	
Timber Damaged		Abandoned Equipment	


S = Item is satisfactory O = Item is not satisfactory (explain in comments)

Blank = Item not inspected NA = not applicable

COMMENTS:

Dozer operator John Cochran at staging area at the end of FR 163 having excavator serviced. Cutter Marty Grove has cut to apex of of the road on the western project area boundary. This area is designated as a landing area, no additional trees designated this inspection, operators want to see how it looks after all designated material is cut. Access to this area can be accomplished through old regeneration cut along established skid roads. One half of double landing area moved to intersection of abandoned gas line and new road right of way.

Discussion with Operator (Date): Dozer operator Cochran informed that he will water bar abandoned gas line upon completion of their use.

Forest Service Inspector: 

Date: 6-3-08

Reviewed: _____