

MARIENVILLE RANGER DISTRICT

OIL AND GAS INSPECTION REPORT

OGM Case Number: 243 Date of Inspection: 05-09-08
 Weather Conditions: cool and overcast Persons On-Site: 2
 Warrant/Lot Number: 2752, Lot 8 Mineral Owner/Leasee: Duhring Resource Co.
 Project: Cut, Skid and Deck Inspector: David Cotterman
 Discussed Operation With: Marty Grove
 Equipment On-Site: TJ skidder
 Activity On-Site: yes

INSPECTION ITEMS and RESOURCE CONCERNS

Erosion		FS System Roads	
Minor oil, gas, brine leak		Non-FS System Roads	
Major oil, gas, brine spill		Drainage Structures	
Safety Hazards		Tank Concerns	
Unauthorized Development		Re-Vegetation	
Well Head Leaks		Slash Disposal	
Sump Ponds		Electric Lines	
Timber Removal		Pipe Lines	
Timber Damaged		Abandoned Equipment	

S = Item is satisfactory O = Item is not satisfactory (explain in comments)

Blank = Item not inspected NA = not applicable

COMMENTS:

Operator Marty Grove has begun cutting, skidding and decking of material associated with OGM Case 243. Operations have begun on the south side of the project area, decking at existing well location/access road. Sawtimber and pulpwood material are being kept in separate decks. Additional trees (2 sawtimber and 16 pulpwood) designated for removal to facilitate landing at two previously approved decking locations.

Discussion with Operator (Date): 5-9-08: separate sawtimber and pulpwood decks, do not mix product, timber specifications (9.6" dib sawtimber and 5.0" dib pulpwood)

Forest Service Inspector: 

Date: 5-12-09

Reviewed: _____