

BRADFORD RANGER DISTRICT

OIL AND GAS INSPECTION REPORT

OGM Case Numbers:		Date of Inspection:	May 3, 2007
Weather Conditions:	Sunny 70 Deg.	Persons On-Site:	Sheldon, Kathleen, Jim S., Bill C., Arthur S.
Warrant/Lot Number:	Lot 7 & 9	Mineral Owner/Leasee:	Duhring Resource
Project:	New Development	Inspector:	S.Winters
Discussed Operation With:	Only FS employees & OGM Owner Duhring		
Equipment On-Site:	N/A		
Activity On-Site:	N/A		

INSPECTION ITEMS and RESOURCE CONCERNS

Thursday morning we met at 9:00 A.M. to review new well development. Arthur S. provided a revised layout for review of (Lot 7) wells # 7-20,7-21,7-22 & 14. After reviewing the road layout there were a few slopes for the roads outside the 8% but they are short runs and I feel they should work. Next we went up the hill to look at new well locations not previously reviewed (were not included in the first submission). Arthur had the roads laid out to what he felt should work but after reviewing we did make some preliminary changes and are presently waiting for review from his road builder to get his thoughts. We then moved to (Lot 9) to review well locations D25,D26,D27,D29,D30,12-1,12-2, 12-3, 12-4. Arthur has made an effort to move some of these wells in order to minimize impacts to the natural resources. After reviewing the road layout for this area I had the same outcome that the road grades were good in most instances. My comment to Arthur was that I'm not completely happy with some of the grades but I feel your doing your best to work with us and the roads should work. The biggest thing we eliminated were the 2 stream crossings with the road to access wells D25, D26, and D27. In a whole the day went well, Arthur and I accomplished a lot of major tasks and have a few more to review. He did mention that he is going to drop well # 7-20 on lot 7.

Forest Service Inspector: Sheldon Winters

Date: _____

Reviewed: _____